Qty:

4 Um:

Each

: STEP WELDMENT

: D2460

: N/A

: D

: D2460 REV D

: 23/04/2009

SAY

09-04-08

Date: User:

Tuesday, 07/04/2009 10:18:09 AM

Julie Dawson

Process Sheet

Drawing Name

Part Number

Material **Due Date**

Description:

Drawing Number

Project Number

Drawing Revision

Customer : CU-DAR001 Dart Helicopters Services

Job Number : 46951 **Estimate Number** : 11123

P.O. Number

This Issue : 07/04/2009

: NC Prsht Rev.

: // First Issue

: 34987 **Previous Run**

Written By

Checked & Approved By

Comment

Additional Product

S.O. No. :

Type

Added Finish as per Rev D 05-11-30 JLM : Est Rev: F

: LARGE FAB ASSY

Job Number:

Seq. #: 1.0

Machine Or Operation:

D2244116

Comment: Qty.: 0.5000 Each(s)/Unit

Pick:

Part# Qty .5

D2244

Description Step Extrusion

Total:

<u>B38023 (1)</u>

204 Step Lug

2.0000 Each(s)

Batch

Step Extrusion

133733 (1)

2.0

D23381

Comment: Qty.: 1.0000 Each(s)/Unit

Pick:

Qty

Part Number

Total:

Batch No.

1

D2338-1

Description End cap

3.0 D23382

204 Step Lug

4.0000 Each(s)

Comment: Qty.:

1.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Pick:

Qty 1

Part Number

D2338-2

Description

End cap

4.0

D2459

Angle

Comment: Qty.:

1

1.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Pick: Qty

Part Number D2459

Description Lug

Dart Aerospace Ltd

W/O:			WORK ORDER CHANGES								
DATE	STEP		PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector			
						İ					
Dort No		•									

Part No:	PAR #:	Fault Category:	NCR: Yes No DQA:	Date:
Resolution:		_ Disposition:	QA: N/C Closed:	Date:

NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
DATE OTED	Descriptio	n of NC		Corrective Action Section B		Verification	Annyoval	A				
DATE	STEP	Section		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
		•										
					·							
		,										
					·							
									,			

NOTE: Date & initial all entries

Tuesday, 07/04/2009 10:18:09 AM Date: Julie Dawson User: **Process Sheet Drawing Name: STEP WELDMENT** Customer: CU-DAR001 Dart Helicopters Services Job Number: 46951 Part Number: D2460 Job Number: Seq. #: Machine Or Operation: Description: LARGE FAB 1 LARGE FABRICATION RESOURCE 1 5.0 PBD **Comment: LARGE FABRICATION RESOURCE 1** 1-Cut D2244 per Dwg. D2460 2-Weld as per Dwg. D2460 (use DT8793 to locate D2459) Batch: <u>19410130</u> m1/0 431 A/R Alum rod 3-Deburr INSPECT WORK TO CURRENT STEP 6.0 QC5 Comment: INSPECT WORK TO CURRENT STEP VISUAL WELDING INSPECTION 7.0 **Comment: VISUAL WELDING INSPECTION** HAND FINISHING RESOURCE #1 8.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 POWDER COATING 9.0 Comment: POWDER COATING Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3 ////0939 START TIME: **OVEN TEMPERATURE:** FINISH TIME: 10.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Wing Walk per dwg D2460 Batch: ///// 0/3

Dart Aerospace

W/O:		Permit changes WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	471	7.1 webs us par as 2004					
7/4/21	471	Alodine 40 pr 0452005 SAD 09-04-21 x4	1	ORPHAI		A	व्हीयारा
	₽7.2	Penne glupia at one end Br welding SAD 09-09-27	W	(4/1/4			Sorlare
	¥73	DENTS BE 333233		1 1.10			Salarla
	774	acq inspect well , PD 09-043	M	4 /4/4			Sorlaile
· · · · · · · · · · · · · · · · · · ·	\$ 7.5	acs impact want to worst sto of offer 23 (XY)	M	u (el t			8 oxlords

Part No:	PAR #:	Fault Category:	 NCR: Yes No	DQA:	Date:
Resolution:	:	Disposition:	 QA: N/C Closed	:	Date:

NCR:		İ	WORK ORDER NON-CONFORMANCE (NCR) Corrective Action Section B									
DATE STE		Description	of NC		Verification	A 1						
	STEP	Section /	A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector			
· · ·												
		İ										
		ī										
		<u> </u>										
									-			

NOTE: Date & initial all entries

Tuesday, 07/04/2009 10:18:09 AM Date: Julie Dawson User: **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: STEP WELDMENT Job Number: 46951 Part Number: D2460 Job Number: Seq. #: **Machine Or Operation:** Description: 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: Inspect Powder Coat and Wing Walk 12.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock 4685 Location: 13.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion

Dart Aerospace Ltd

W/O:		WORK ORDER	WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE	Ву	Ву	By Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector						
			¢											
				<u> </u>										

Part No:		PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
	Resolution:		Disposition:	QA: N/C Closed	:	Date:

NCR: WORK ORDER NON-CONFORMANCE (NCR)									
	Description	n of NC		Corrective Action Section B		Verification	Ammanual	Ammanal	
DATE	STEP Descriptio	Section	1 A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		·	·						
									.,
							``		
		,							
			•						

NOTE: Date & initial all entries

